

U.S. Army Military History Institute
950 Soldiers Drive
Carlisle Barracks, PA 17013-5021
9 Aug 2011

Equipment

IN-THEATER EQUIPMENT MODIFICATIONS

A Working Bibliography of MHI Sources

CONTENTS

WWII.....p.1
Korea.....p.1
Vietnam.....p.2

WWII

Organ, Francis P. "Doodlebug at Tinian." Military Engineer (Aug 1945): pp. 315-16. Per.
LVT adapted for steep coral cliffs by protruding steel & wood beams.

See also:

-Bibliographies on Hedgerow Cutter in Armor-WWII-Overview and Tank Dozers in Armor-WWII.

KOREAN WAR

Peifer, William H. Supply by Sky: The Quartermaster Airborne Development, 1950-1953. Wash, DC:
Hist Branch, OQMG, 1957. UC34.A2ser2no2.
See Chap V on parachute development.

U.S. Army. Far East and Eighth U.S. Army. Logistics in the Korean Operations. Vol. 4. Japan, n.d.
DS920.5.L6.L63.
See Chap VII, pp. 7-8 on napalm land mines and Chap VIII, pp. 6-7 for specific
equipment modified by Operations ROLLUP and REBUILD.

U.S. Army. Japan Logistical Command. Operation Rollup; Operation Rebuild. Report, 1952. 85 p.
UC263.O63.
Surplus WW2 equipment collected from western Pacific islands collected and refitted for
use.

VIETNAM WAR

Greenberg, Lawrence M. "...Rome Plow Company..." Vietnam (Feb 1991): pp. 12, 16 & 66. Per. Special blades on D7E bulldozers in Vietnam.

Hay, John H., Jr. Tactical and Materiel Innovations. Wash, DC: Dept of Army, 1974. 197 p. DS557.7S9H44.

Replete with examples of large and small equipment; for example p. 21 on the Nighthawk Helicopter & pp. 36-38 on riot control agents.

Heiser, Joseph M., Jr. Logistic Support. Wash, DC: Dept of the Army, 1974. 273 p. DS554.52.H4. See p. 53 on Project ENSURE (Expediting Non-Standard Urgent Requirements for Equipment).

Ploger, Robert R. U.S. Army Engineers, 1965-1970. Wash, DC: Dept of the Army, 1974. 240 p. DS554.45.P55.

See pp. 95-100 on Rome Plow.

U.S. Army. Concept Team in Vietnam. Final Report Field Expedient Systems in Use by Army Aviation in RVN. n.p., 1971. ca 110 p. DS558.8.F53

U.S. Army. Vietnam. Mechanized and Armor Combat Operations in Vietnam. n.p., 1967. 203 p. DS558.9.A75.M43

See pp. 171-175 on the M48A3 Tank, M113 Personnel Carrier & Rome Plow.

U.S. Military Assistance Command, Vietnam. "MACV Significant Problem Areas Report," dated 5 Nov 1970. ca 20 p. MACV Command Historians' Collection, Arch.

See pp. II-1 - II-2 on specific equipment problems.